






# Nunapitchuk Washeteria

By Juliana Wassillie

# North Side of Washeteria



# Washeteria Services

-  Water for the whole community
-  Washers and dryers
-  Watering point for self service
-  Sauna
-  Showers



# Chemical Mixing Area





# Sauna Room



- 🌐 Made of lumber
- 🌐 Backwashed water enters through the pipe
- 🌐 Has two entrances

# Sauna Entryway





# Restrooms/Shower Room





# Wall Cracks



- 🌐 Cracks all around the building
- 🌐 Cold wind seeps through
- 🌐 Covered in goop

# Exit signs





# Maintenance Area





# Back Door



- 🌐 Cannot open completely
- 🌐 Stairway is unleved

# Water Hose





# Water Service Control Panel



- Set up inside water operator's office
- Hassle for water/sewer boys
- Has a live wire below the panel



# Day Tank and No Outlet





# Ventilation



# Washer/Dryer Area



- 🌐 Five Washers
- 🌐 Two Dryers
- 🌐 Three Benches
- 🌐 Two Tables



# Benches and Tables Gaps



# Drain Pipes Rotting





# Rotting Foundation



# Bulk Fuel Tanks



- Single Walled
- Have to level the dykes every couple years
- The tank liner has many holes




# Improvements

- 🌐 Larger washers and more dryers
- 🌐 Sauna room away from backwashing pipe
- 🌐 Water service panel moved outside the office
- 🌐 Shelves for chemicals
- 🌐 Double walled bulk fuel tanks
- 🌐 Ramp for handicap access
- 🌐 Outlet outside the building and better water access

# In Conclusion

- 🌐 Many people rely on the Washeteria for washers/dryers, sauna, and water
- 🌐 Residents are not able to afford their own washers/dryers
- 🌐 Some residents do not own a steam bath (sauna)





# Nunapitchuk Washeteria

By Juliana Wassillie